

TYPICAL REPAIR TIMES

**FAIRCHILD AVIATION RECORDERS
SOLID STATE COCKPIT VOICE RECORDER**

FAIRCHILD MODEL FA2100SSCVR

The following time values (in hours) have been established as adequate to perform the following functions:

- A. Test Recorder, determine cause of failure. Remove dust cover for board access, close unit and test to TSO-C123a compliance. 2.0

- B. Add for specific repair functions:
 - 1. Determine defective board and replace 0.5
 - 2. Replacement of Memory Module 0.5

Time allowance for other repair functions to be determined individually.

L-3 COMMUNICATIONS
AVIATION RECORDERS
P.O. BOX 3041
SARASOTA, FLORIDA 34230
TEL: (941) 371-0811
FAX: (941) 377-5591
SITA: SRQLFCR